




-
-
-
-
-
-
-
-



Series	A	B	C	D (pin1&4)	D (pin2&3)	E1	E2



Series	a	b	c	d	e	f

Part No	Inductance @ 500KHz/0.25V (nH)	Tolerance	Temperature Rise Current Typ. (A) 1-4	Current Typ. (A) 1-4	DC Resistance ±10% 1-4	DC Resistance ±10% 2-3

Part No	Inductance @ 100KHz/1V (nH)	Tolerance	Temperature Rise Current Typ. (A) 1-4	Current Typ. (A) 1-4	DC Resistance ±10% 1-4	DC Resistance ±10% 2-3




Part No	Inductance @ 100KHz/0.1V (nH)	Tolerance	Temperature Rise Current Typ. (A) 1-4	Current Typ. (A) 1-4	DC Resistance ±10% 1-4	DC Resistance ±10% 2-3

△

:

Marking	Printing (Inductance)
---------	-----------------------

:



:

•

•

•

•

•

•

•

•